


TPMC Photo Specificaiton for FCL (Full Container Loading) - Steel Pipes

Sr.No.	Process	Reference Photos		
1	Empty Container Photos	<p>1. Internal floor and sides</p> 	<p>2. Half-open container door</p> 	<p>3. Closed container door</p> 
2	Container Yard Entry Photos	<p>1. Photo before unloading</p> 	<p>2. Clear shipping mark and tag</p> 	<p>3. Photo after unloading (if applicable)</p> 
3	Loading Photos (Note: Protect the coating)	<p>1. Photo after loading each layer</p> 	<p>2. Photo when half-full</p> 	<p>3. Photo when fully loaded</p> 
4	Product Securing and Lashing Photos	<p>1. Cargo fully loaded and no lashing required</p> 	<p>2. Partially loaded with 2 straps</p> 	<p>3. Secured with 2 or 4 steel straps</p> 
5	Sealing Photos	<p>1. Photo of the seal number</p> 	<p>2. Photo of closing the container door</p> 	<p>3. Photo of locking the seal</p> 